

中国科学院国家天文台兴隆观测基地

2.16 米天文望远镜

OMR 定标灯谱线证认手册

The Spectral Atlas of OMR Wavelength Calibration Lamps

任娟娟 李红斌 赵勇 范舟 王汇娟

Juanjuan Ren, Hongbin Li, Yong Zhao,

Zhou Fan, Huijuan Wang

(2017. 11. 18)

Contents

HeAr (150 lp/mm, blazed at 6400Å, Red band, Center = 6400Å)	1
HeAr (300 lp/mm, blazed at 6000Å, Blue band, Center = 6000Å)	4
HeAr (300 lp/mm, blazed at 7500Å, Red band, Center = 7500Å)	7
HeAr (600 lp/mm, blazed at 4600Å, Blue band, Center = 4600Å)	10
HeAr (600 lp/mm, blazed at 6600Å, Center = 6600Å)	12
HeAr (600 lp/mm, blazed at 8800Å, Center = 8800Å)	14
HeAr (1200 lp/mm, blazed at 4000Å, Blue band, Center = 4000Å)	16
HeAr (1200 lp/mm, blazed at 5000Å, Blue band, Center = 5000Å)	17
HeAr (1200 lp/mm , blazed at 6200Å, Median band, Center = 6200Å) ...	18
HeAr (1200 lp/mm, blazed at 7300Å, Red band, Center = 7300Å)	19
HeAr (1200 lp/mm, blazed at 8300Å, Red band, Center = 8300Å)	20
HeAr (1200 lp/mm, blazed at 9300Å, Red band, Center = 9300Å)	21
FeAr (150 lp/mm, blazed at 6400Å, Red band, Center = 6400Å)	22
FeAr (300 lp/mm, blazed at 6000Å, Blue band, Center = 6000Å)	25
FeAr (300 lp/mm, blazed at 7500Å, Red band, Center = 7500Å)	28
FeAr (600 lp/mm, blazed at 4600Å, Blue band, Center = 4600Å)	31
FeAr (600 lp/mm, blazed at 6600Å, Red band, Center = 6600Å)	34
FeAr (600 lp/mm, blazed at 8800Å, Center = 8800Å)	37
FeAr (1200 lp/mm, blazed at 4000Å, Blue band, Center = 4000Å)	39
FeAr (1200 lp/mm, blazed at 5000Å, Blue band, Center = 5000Å)	42

FeAr (1200 lp/mm, blazed at 6200Å, Median band, Center = 6200Å) ...	45
FeAr (1200 lp/mm, blazed at 7300Å, Red band, Center = 7300Å)	48
FeAr (1200 lp/mm, blazed at 8300Å, Red band, Center = 8300Å)	49
FeAr (1200 lp/mm, blazed at 9300Å, Red band, Center = 9300Å)	50
FeNe (150 lp/mm, blazed at 6400Å, Red band, Center = 6400Å)	51
FeNe (300 lp/mm, blazed at 7500Å, Center = 7500Å)	52
FeNe (600 lp/mm, blazed at 4600Å, Red band, Center = 4600Å)	53
FeNe (600 lp/mm, blazed at 6600Å, Center = 6600Å)	54
FeNe (600 lp/mm, blazed at 8800Å, Center = 8800Å)	55
FeNe (1200 lp/mm, blazed at 6200Å, Median band, Center = 6200Å)....	56
FeNe (1200 lp/mm, blazed at 7300Å, Red band, Center = 7300Å)	57
FeNe (1200 lp/mm, blazed at 8300Å, Red band, Center = 8300Å)	58

















































































































